

Professional Audio Service Bulletin

Mincom
Division



BULLETIN NO. 1

SUBJECT: Signal Electronics PC Board FET Replacement

APPLICABLE TO: All M-79 Signal Electronic PC Boards which use Motorola FET'S

PURPOSE: To improve the reliability of the Signal Electronics PC Boards

REQUIRED PARTS: Transistor 2N4342 or 2N4343, Manufactured by Fairchild or National ONLY, Mincom Catalog No. 83-1530-2462

PROCEDURE:

- I. Replace all Motorola 2N4342 transistors on the signal electronic PC board with Fairchild or National components.
- II. Change the Instruction Manual signal electronic PC board parts list to read FAIRCHILD or NATIONAL instead of MOTOROLA for Q10, Q11, Q18, Q19, Q20, Q25, Q26, Q27, Q28, Q34 and Q35.

MANDATORY

November 1973

Professional Audio Service Bulletin



Bulletin No.
Date

BULLETIN NO. 1

SUBJECT: Signal Electronics PC Board FET Replacement

APPLICABLE TO: All M-79 Signal Electronic PC Boards which use Motorola FET'S

PURPOSE: To improve the reliability of the Signal Electronics PC Boards

REQUIRED PARTS: Transistor 2N4342 or 2N4343, Manufactured by Fairchild or National ONLY, Mincom Catalog No. 83-1530-2462

PROCEDURE:

- I. Replace all Motorola 2N4342 transistors on the signal electronic PC board with Fairchild or National components.
- II. Change the Instruction Manual signal electronic PC board parts list to read FAIRCHILD or NATIONAL instead of MOTOROLA for Q10, Q11, Q18, Q19, Q20, Q25, Q26, Q27, Q28, Q34 and Q35.